



DIS Sensors bv

Oostergracht 40

3763 LZ Soest | The Netherlands

T +31 (0)35 - 603 81 81

M info@dis-sensors.com

W www.dis-sensors.com

Firmware release notes for sensor family: QG40N Tiltswitch

| Known issue, scheduled for new releases | Temporary workaround |
|---|----------------------|
| | |
| | |
| | |

| Firmware version number | Changes with respect to previous version | Date of release |
|-------------------------|--|-----------------|
| | | |
| V12.01 | In rare cases the CRC of EEPROM blocks A and B get corrupted while configuring the sensor, not in normal operation | 20200107 |
| V12.00 | Support added for MEMS-chip successor, backwards compatible | 20200511 |